## - Site Service Report -

January 10, 2012

IRD SO#: 11167 IRD Ref: To:ESS

**Project Name:LTTP TN-1** 

Project Location: I-40 mm 91.5 near Jackson, TN

Service Date(s): June 1, 2011

Weather: 37°Celsius

Job Description: Annual maintenanace

## **Work Completed:**

- Loops, kistlers, piezos and cabinet visually inspected
- Lane 1 sensor 1 and lane 2 sensor 1 are disabled
- iSINC components working as expected
- cleaned and reseated ISINC hardware
- Tested all kistlers and loops
- Downstream loop in lane 4 has a fluctuating resistance, but is still working for now
- Checked power supplies, all within spec
- Observed vehicle display for some time and saw no errors
- Had Rey Castro dial up site before leaving, worked as expected

Work Remaining: Install new kistler in lane 1 and 2, downstream loop in lane 4 should be replaced as well

Parts Used: None

Mileage / Travel Time: 802 miles round trip/ 14 hrs total travel

Time Spent on Site: 2 hours

Notes:

## **Action Items:**

Item	Action Required	Ownership
1.	Install new kistlers lane 1 and 2, replace lane 4 downstream loop	СМа





